

07 June 2021  
300505868

## Security Advisory for FL SWITCH SMCS series

### Advisory Title

Multiple vulnerabilities have been discovered in the current firmware of the PHOENIX CONTACT FL SWITCH SMCS series switches.

### Advisory ID

CVE-2021- 20003  
CVE-2021- 20004  
CVE-2021- 20005  
VDE-2021-023

### Vulnerability Description

TCP-Fragmentation DoS vulnerability (CVE-2021- 20003, CWE-404):  
Fragmented TCP-Packets may cause a Denial of Service of Web-, SNMP-, and ICMP Echo-service. The switching functionality of the device is not affected.

LLDP XSS vulnerability (CVE-2021- 20004, CWE-79):  
An attacker may insert malicious code via LLDP frames into the web-based management which could then be executed by the client.

Urgent-Flag DoS vulnerability (CVE-2021- 20005, CWE-362):  
If an attacker sends a hand-crafted TCP-Packet with the Urgent-Flag set and the Urgent-Pointer set to 0, the network stack will crash. The device needs to be rebooted afterwards.

### **Affected products**

Article no	Article	Affected versions
2700996	FL SWITCH SMCS 16TX	<= 4.70
2700997	FL SWITCH SMCS 14TX/2FX	<= 4.70
2701466	FL SWITCH SMCS 14TX/2FX-SM	<= 4.70
2891123	FL SWITCH SMCS 8GT	<= 4.70
2891479	FL SWITCH SMCS 6GT/2SFP	<= 4.70
2989103	FL SWITCH SMCS 8TX-PN	<= 4.70
2989093	FL SWITCH SMCS 4TX-PN	<= 4.70
2989226	FL SWITCH SMCS 8TX	<= 4.70
2989323	FL SWITCH SMCS 6TX/2SFP	<= 4.70
2700290	FL SWITCH SMN 6TX/2POF-PN	<= 4.70
2989501	FL SWITCH SMN 8TX-PN	<= 4.70
2989543	FL SWITCH SMN 6TX/2FX	<= 4.70
2989556	FL SWITCH SMN 6TX/2FX SM	<= 4.70
2989365	FL NAT SMN 8TX	<= 4.63
2702443	FL NAT SMN 8TX-M	<= 4.63

### **Impact**

An attacker may use the vulnerabilities described above to provoke a denial of service to defeat certain management functions of the device or use the XSS vulnerability to attack the client PC.

### **Classification of Vulnerability**

TCP-Fragmentation DoS vulnerability (CVE-2021- 20003):

Base Score: 5.3

Vector: CVSS:3.0/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:L

LLDP XSS vulnerability (CVE-2021- 20004):

Base Score: 7.4

Vector: CVSS:3.0/AV:A/AC:L/PR:N/UI:R/S:C/C:L/I:H/A:N

Urgent-Flag DoS vulnerability (CVE-2021- 20005):

Base Score: 7.5

Vector: CVSS:3.0/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H

### **Temporary Fix / Mitigation**

Phoenix Contact recommends operating network-capable devices in closed networks or protected with a suitable firewall. For detailed information on our recommendations for measures to protect network-capable devices, please refer to our application note:

[Measures to protect network-capable devices with Ethernet connection](#)

### **Acknowledgement**

These vulnerabilities have been discovered and reported by Anne Borchering, Fraunhofer-Institut für Optronik, Systemtechnik und Bildauswertung IOSB.

We kindly appreciate the coordinated disclosure of this vulnerability by the finder.

PHOENIX CONTACT thanks CERT@VDE for the coordination and support with this publication.