

2020-02-24
300440147/pbsa56

Security Advisory for Automation Worx Software Suite – Update 2020-02-24

Advisory Title

Phoenix Contact Automationworx BCP File Parsing:
Uninitialized Pointer Remote Code Execution Vulnerability, Use-After-Free Remote Code
Execution Vulnerability and Out-Of-Bounds Read Information Disclosure Vulnerability

Advisory ID

VDE-2019-014

CVE-2019-12869 (ZDI-CAN-7781)
CVE-2019-12870 (ZDI-CAN-7784)
CVE-2019-12871 (ZDI-CAN-7780, ZDI-CAN-7785, ZDI-CAN-7786)

Vulnerability Description

A manipulated PC Worx or Config+ project file could lead to a remote code execution.
The attacker needs to get access to an original PC Worx or Config+ project file to be able to
manipulate it. After manipulation the attacker needs to exchange the original file by the
manipulated one on the application programming workstation.

Affected products

Following components of Automationworx Software Suite version 1.86 and earlier are affected:

- PC Worx
- PC Worx Express
- Config +

Impact

Availability, integrity, or confidentiality of an application programming workstation might be compromised by attacks using these vulnerabilities.

Automated systems in operation which were programmed with one of the above-mentioned products are **not** affected.

Classification of Vulnerability

ZDI-CAN-7780, -7784, -7785, -7786:

Base Score: 7.8

Vector: CVSS: AV:L/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H

ZDI-CAN-7781:

Base Score: 3.3

Vector: CVSS: AV:L/AC:L/PR:N/UI:R/S:U/C:L/I:N/A:N

Temporary Fix / Mitigation

We strongly recommend customers to exchange project files only using secure file exchange services.

Project files should not be exchanged via unencrypted email.

Remediation

With the next version of Automationworx Software Suite the following measures will be implemented:

- The zlib component will be updated to the latest version (1.2.11.0). By utilizing the latest version of zlib a manipulated BCP file is detected as corrupt. The unpacking operation is aborted and therefor the remote code execution is precluded.
- The validation of input data will be improved.
- Objects in the affected software components will be completely initialized.
- Further 3rd party components will be checked for known vulnerabilities and will be exchanged or updated if required.
- General preventive security measures will be implemented such as address space layout randomization.

Update 2020-02-24: Above-mentioned improvements have been implemented in Automationworx Software Suite 1.87 which is available for [download](#) now.

Acknowledgement

The vulnerabilities were discovered by 9sg Security Team.
Reported through Zerodayinitiative.
Coordinated by NCCIC and CERT@VDE.