

14 June 2022
300546915

Security Advisory for FL MGUARD, TC MGUARD, mGuard Device Manager and FL WLAN devices

Publication Date: 2022-04-12
Last Update: 2022-06-14
Current Version: V1.1

Advisory Title

A critical vulnerability has been discovered in the OpenSSL library, which is utilized in Phoenix Contact FL MGUARD, TC MGUARD devices, mGuard Device Manager and FL WLAN devices.

Advisory ID

[CVE-2022-0778](#)
[VDE-2022-013](#)

Vulnerability Description

FL MGUARD and TC MGUARD devices are affected by a possible infinite loop within an OpenSSL library method for parsing elliptic curve parameters. This method is used on parsing cryptographic certificates that contain elliptic curve public keys in compressed form, which may occur on:

- Parsing client certificates for HTTPS administrative login
- Parsing client certificates for SSH administrative login
- Parsing peer certificates for IPsec VPN connections
- Parsing certificates of external servers, including:
 - OpenVPN server
 - Configuration pull server

Personally liable partner:
Phoenix Contact Verwaltungs GmbH
Amtsgericht Lemgo HRB 5273
Kom. Ges. Amtsgericht Lemgo HRA 3746

Group Executive Board:
Frank Stührenberg (CEO)
Dirk Görlitzer, Torsten Janwlecke
Ulrich Leidecker
Frank Possel-Dölken, Axel Wachholz

Deutsche Bank AG
(BLZ 360 700 50) 226 2665 00
BIC: DEUTDE33XXX
IBAN:
DE93 3607 0050 0226 2665 00

Commerzbank AG
(BLZ 476 400 51) 226 0396 00
BIC: COBADE33XXX
IBAN:
DE31 4764 0051 0226 0396 00

- Update server

Attackers could try to exploit the vulnerability from remote.

For the mGuard Device Manager only the mdm Installer for Windows is affected.

On FL MGUARD 1102 and FL MGUARD 1105 with mGuardNT 1.5.2 and older, the device can be affected through an adapted certificate. This can occur on connection with a remote logging server, configured for certificate authentication, or an remote authentication server at certificate based authentication.

Affected products

| Article no | Article | Affected versions | Fixed version |
|------------|-------------------------------|-------------------|--------------------------|
| 2700642 | FL MGUARD RS2000 TX/TX VPN | <= 8.8.5 | Download |
| 2701875 | FL MGUARD RS2005 TX VPN | <= 8.8.5 | Download |
| 2903441 | TC MGUARD RS2000 3G VPN | <= 8.8.5 | Download |
| 2700634 | FL MGUARD RS4000 TX/TX | <= 8.8.5 | Download |
| 2200515 | FL MGUARD RS4000 TX/TX VPN | <= 8.8.5 | Download |
| 2701876 | FL MGUARD RS4004 TX/DTX | <= 8.8.5 | Download |
| 2701877 | FL MGUARD RS4004 TX/DTX VPN | <= 8.8.5 | Download |
| 2903440 | TC MGUARD RS4000 3G VPN | <= 8.8.5 | Download |
| 2702139 | FL MGUARD RS2000 TX/TX-B | <= 8.8.5 | Download |
| 2702259 | FL MGUARD RS4000 TX/TX-P | <= 8.8.5 | Download |
| 2702470 | FL MGUARD RS4000 TX/TX-M | <= 8.8.5 | Download |
| 2701274 | FL MGUARD PCI4000 | <= 8.8.5 | Download |
| 2701275 | FL MGUARD PCI4000 VPN | <= 8.8.5 | Download |
| 2701277 | FL MGUARD PCIE4000 | <= 8.8.5 | Download |
| 2701278 | FL MGUARD PCIE4000 VPN | <= 8.8.5 | Download |
| 2700967 | FL MGUARD DELTA TX/TX | <= 8.8.5 | Download |
| 2700968 | FL MGUARD DELTA TX/TX VPN | <= 8.8.5 | Download |
| 2700640 | FL MGUARD SMART2 | <= 8.8.5 | Download |
| 2700639 | FL MGUARD SMART2 VPN | <= 8.8.5 | Download |
| 2702884 | FL MGUARD CORE TX | <= 8.8.5 | Download |
| 2702831 | FL MGUARD CORE TX VPN | <= 8.8.5 | Download |
| 1053405 | FL MGUARD SMART2 VPN/K1 | <= 8.8.5 | Download |
| 1053403 | FL MGUARD RS4000 TX/TX VPN/K1 | <= 8.8.5 | Download |
| 1073940 | FL MGUARD PCIE4000 VPN/K2 | <= 8.8.5 | Download |
| 1073943 | FL MGUARD RS4000 VPN/K2 | <= 8.8.5 | Download |
| 1073944 | FL MGUARD PCI4000 VPN/K2 | <= 8.8.5 | Download |
| 2903588 | TC MGUARD RS2000 4G VPN | <= 8.8.5 | Download |
| 2903586 | TC MGUARD RS4000 4G VPN | <= 8.8.5 | Download |
| 1010461 | TC MGUARD RS4000 4G VZW VPN | <= 8.8.5 | Download |
| 1010462 | TC MGUARD RS2000 4G VZW VPN | <= 8.8.5 | Download |
| 1010463 | TC MGUARD RS4000 4G ATT VPN | <= 8.8.5 | Download |
| 1010464 | TC MGUARD RS2000 4G ATT VPN | <= 8.8.5 | Download |

| | | | |
|---------|-------------------------------|-------------|--------------------------|
| 2700197 | FL MGUARD GT/GT | <= 8.8.5 | Download |
| 2700198 | FL MGUARD GT/GT VPN | <= 8.8.5 | Download |
| 2702547 | FL MGUARD CENTERPORT | <= 8.8.5 | Download |
| 2702820 | FL MGUARD CENTERPORT VPN-1000 | <= 8.8.5 | Download |
| 2981974 | FL MGUARD DM UNLIMITED | <= 1.13.0.1 | Download |
| 2702899 | FL WLAN 1010 | <= 2.70 | |
| 2702900 | FL WLAN 1011 | <= 2.70 | |
| 2702534 | FL WLAN 1100 | <= 2.70 | |
| 2702538 | FL WLAN 1101 | <= 2.70 | |
| 1119246 | FL WLAN 2010 | <= 2.70 | |
| 1119248 | FL WLAN 2011 | <= 2.70 | |
| 2702535 | FL WLAN 2100 | <= 2.70 | |
| 2702540 | FL WLAN 2101 | <= 2.70 | |
| 2700718 | FL WLAN 5100 | <= 3.21 | |
| 2701093 | FL WLAN 5101 | <= 3.21 | |
| 2701850 | FL WLAN 5102 | <= 3.21 | |
| 1043193 | FL WLAN 5110 | <= 3.21 | |
| 1043201 | FL WLAN 5111 | <= 3.21 | |
| 1153079 | FL MGUARD 1102 | <= 1.5.2 | Download |
| 1153078 | FL MGUARD 1105 | <= 1.5.2 | Download |

Impact

By sending a crafted certificate, attackers may trigger an infinite loop in the receiving service. This may cause the service to become unavailable. Additionally, the availability of other services may be reduced due to high CPU load.

Classification of Vulnerability

[CVE-2022-0778](#)

CVSSv3.1 Base Score: 7.5

CVSSv3.1 Vector: [AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H](#)

[CWE-835](#)

FL MGUARD and TC MGUARD may be vulnerable in the following setups:

- Activated HTTPS administrative access with certificate-based authentication
- Activated SSH administrative access with certificate-based authentication
- Use of IPsec VPN connections with certificate-based authentication
- Use of connections to external servers with certificate-based authentication, including:
 - OpenVPN server
 - Configuration pull server
 - Update server

FL WLAN may be vulnerable in the following setup:

- WLAN Client modes with activated certificate-based RADIUS server authentication

The services can be vulnerable, even when they are not configured to use elliptic curve cryptography explicitly.

Temporary Fix / Mitigation

To reduce the possibility of an attack, affected functionality could be deactivated or used only in a way that it is not exposed on untrusted interfaces.

Remediation

This vulnerability is fixed in firmware version 8.8.6. We strongly recommend all affected FL MGUARD and TC MGUARD users to upgrade to this or a later version. FL MGUARD 1102 and FL MGUARD 1105 should be upgraded to version 1.6.0 or higher, which fixes this vulnerability.

PHOENIX CONTACT strongly recommends upgrading FL MGUARD DM UNLIMITED to version 1.13.0.2 or higher, which fixes this vulnerability.

For FL WLAN devices the vulnerability will be fixed in the next regular release. A release date is not yet defined.

Acknowledgement

We kindly appreciate the coordinated disclosure of this vulnerability by the finder.

PHOENIX CONTACT thanks CERT@VDE for the coordination and support with this publication.

History

V1.0 (2022-04-12): Initial publication

V1.1 (2022-06-14): FL MGUARD 1102 and 1105 added