

# VDE-2026-023: Phoenix Contact: Several products are affected by vulnerabilities found in OpenSSL

Publisher: Phoenix Contact GmbH & Co. KG	Document category: csaf_security_advisory
Initial release date: Wed Apr 22 08:00:00 CEST 2026	Engine: 2.5.44
Current release date: Wed Apr 22 08:00:00 CEST 2026	Build Date: Tue Apr 07 12:35:14 CEST 2026
Current version: 1.0.0	Status: FINAL
CVSSv3.1 Base Score: 9.8	Severity: <a href="#">High</a>
Original language:	Language: en-US
Also referred to: VDE-2026-023, PCSA-2026-00001	

## Summary

Attacks are possible when installing key files and digitally signed objects. These attacks can only be carried out if these files are uploaded and installed by a logged-in user with high privileges.

## General Recommendation

Phoenix Contact recommends operating network-capable devices in closed networks or protected with a suitable firewall. For detailed information on our recommendations for measures to protect network-capable devices, please refer to our [application note](#).

## Impact

A successful attack using manipulated firmware or key files (PKCS#12) can lead to the execution of malicious code. This can jeopardize confidentiality, integrity and availability.

## Mitigation

Phoenix Contact strongly recommends to upload firmware or key files (PKCS#12) only from trusted source and to thoroughly check the SHA256 checksum of the files to be uploaded.

## Remediation

Phoenix Contact strongly recommends to upgrade affected devices to the fixed firmware as soon as it gets available.

Article family	Versionsnummer des Fix	Fix available	Planned release date
CHARX control modular SEC-3XXX	1.9.0	yes	
PLCnext Control	2024.0.17	yes	
PLCnext Control AXC F 2000 EA	2026.0.0	yes	
Energy AXC PU	V04.27.00.00	no	2026-08-31
SMART RTU AXC SG	V01.11.00.00	no	2026-09-30
SMART RTU AXC IG	V01.04.00.00	no	2026-12-31
ILC 2250, CATAN C1	Emalytics-1.12.3	no	2026-05-31
ILC 2050	Emalytics-1.12.4	no	2026-09-30
FL MGuard 2xxx, 4xxx	10.6.1	yes	
FL SWITCH 2xxx, FL NAT 2xxx, FL SWITCH TSN 23xx, FL SWITCH 59xx	3.57	no	2026-06-29
FL WLAN 1xxx, FL WLAN 23xx	26.06.00	no	2026-06-29
TC ROUTER 2xxx, 3xxx, TC CLOUD CLIENT 1002-4G	3.8.9	yes	
TC ROUTER 5004T-5G EU	1.6.24	yes	
CLOUD CLIENT 1101-TX/TX, TC CLOUD CLIENT 1002-TX/TX	3.7.8	yes	
TC ROUTER 4xxx	5.0.72.102	no	2026-04-30
FL TIMESERVER NTP	5.0.71.101	no	2026-08-31
CELLULINK x401-4G	2025.6.3	yes	

## Product Description

Phoenix Contact industrial routers, access points and switches, security appliances, charge controllers and SPS controllers.

## Affected Product(s)

Article	Name	Affected	Fixed
<a href="#">1138965</a>	CHARX SEC-3150	Firmware <1.9.0	1.9.0
<a href="#">1139012</a>	CHARX SEC-3100	Firmware <1.9.0	1.9.0
<a href="#">1139018</a>	CHARX SEC-3050	Firmware <1.9.0	1.9.0
<a href="#">1139022</a>	CHARX SEC-3000	Firmware <1.9.0	1.9.0
<a href="#">1151412</a>	AXC F 1152	Firmware <2024.0.17	Firmware 2024.0.17
<a href="#">2404267</a>	AXC F 2152	Firmware <2024.0.17	Firmware 2024.0.17
<a href="#">1079808</a>	GTC F 2172	Firmware <2024.0.17	Firmware 2024.0.17
<a href="#">1069208</a>	AXC F 3152	Firmware <2024.0.17	Firmware 2024.0.17
<a href="#">1051328</a>	RFC 4072S	Firmware <2024.0.17	Firmware 2024.0.17
<a href="#">1050841</a>	NFC 482S	Firmware <2024.0.17	Firmware 2024.0.17

Article	Name	Affected	Fixed
<a href="#">1246285</a>	BPC 9102S	Firmware <2024.0.17	Firmware 2024.0.17
<a href="#">1136419</a>	RFC 4072R	Firmware <2024.0.17	Firmware 2024.0.17
<a href="#">1551772</a>	AXC F 2000 EA	Firmware <2026.0.0	Firmware 2026.0.0
<a href="#">1264327</a>	Energy AXC PU	Firmware <V04.27.00.00	
<a href="#">1110435</a>	SMART RTU AXC SG	Firmware <V01.11.00.00	
<a href="#">1264328</a>	SMART RTU AXC IG	Firmware <V01.04.00.00	
<a href="#">2403160</a>	ILC 2050 BI	Firmware <1.12.4	
<a href="#">2404671</a>	ILC 2050 BI-L	Firmware <1.12.3	
<a href="#">1541303</a>	ILC 2250 BI	Firmware <1.12.3	
<a href="#">1535543</a>	ILC 2250 BI-L	Firmware <1.12.3	
<a href="#">1371432</a>	CATAN C1 EN	Firmware <1.12.3	
<a href="#">1357828</a>	FL MGuard 2102	Firmware <10.6.1	Firmware 10.6.1
<a href="#">1357850</a>	FL MGuard 2105	Firmware <10.6.1	Firmware 10.6.1
<a href="#">1357840</a>	FL MGuard 4302	Firmware <10.6.1	Firmware 10.6.1
<a href="#">1357875</a>	FL MGuard 4305	Firmware <10.6.1	Firmware 10.6.1
<a href="#">1357842</a>	FL MGuard 4102 PCIE	Firmware <10.6.1	Firmware 10.6.1
<a href="#">1441187</a>	FL MGuard 4102 PCI	Firmware <10.6.1	Firmware 10.6.1
<a href="#">1488318</a>	FL MGuard 4302/K1	Firmware <10.6.1	Firmware 10.6.1
<a href="#">1427378</a>	FL MGuard 4102 PCIE/K2	Firmware <10.6.1	Firmware 10.6.1
<a href="#">1488314</a>	FL MGuard 4102 PCI/K2	Firmware <10.6.1	Firmware 10.6.1
<a href="#">1427379</a>	FL MGuard 4302/K2	Firmware <10.6.1	Firmware 10.6.1
<a href="#">1488325</a>	FL MGuard 4302/K3	Firmware <10.6.1	Firmware 10.6.1
<a href="#">1488326</a>	FL MGuard 4302/K4	Firmware <10.6.1	Firmware 10.6.1
<a href="#">1696708</a>	FL MGuard 4302/KX	Firmware <10.6.1	Firmware 10.6.1
<a href="#">1696779</a>	FL MGuard 4305/KX	Firmware <10.6.1	Firmware 10.6.1
<a href="#">2702323</a>	FL SWITCH 2005	Firmware <3.57	
<a href="#">2702324</a>	FL SWITCH 2008	Firmware <3.57	
<a href="#">1106707</a>	FL SWITCH 2008F	Firmware <3.57	
<a href="#">2702903</a>	FL SWITCH 2016	Firmware <3.57	
<a href="#">2702665</a>	FL SWITCH 2105	Firmware <3.57	
<a href="#">2702666</a>	FL SWITCH 2108	Firmware <3.57	
<a href="#">2702908</a>	FL SWITCH 2116	Firmware <3.57	
<a href="#">2702334</a>	FL SWITCH 2204-2TC-2SFX	Firmware <3.57	
<a href="#">2702326</a>	FL SWITCH 2205	Firmware <3.57	

Article	Name	Affected	Fixed
<a href="#">2702330</a>	FL SWITCH 2206-2FX	Firmware <3.57	
<a href="#">2702331</a>	FL SWITCH 2206-2FX SM	Firmware <3.57	
<a href="#">2702333</a>	FL SWITCH 2206-2FX SM ST	Firmware <3.57	
<a href="#">2702332</a>	FL SWITCH 2206-2FX ST	Firmware <3.57	
<a href="#">2702969</a>	FL SWITCH 2206-2SFX	Firmware <3.57	
<a href="#">1044028</a>	FL SWITCH 2206-2SFX PN	Firmware <3.57	
<a href="#">1095628</a>	FL SWITCH 2206C-2FX	Firmware <3.57	
<a href="#">2702328</a>	FL SWITCH 2207-FX	Firmware <3.57	
<a href="#">2702329</a>	FL SWITCH 2207-FX SM	Firmware <3.57	
<a href="#">2702327</a>	FL SWITCH 2208	Firmware <3.57	
<a href="#">1044024</a>	FL SWITCH 2208 PN	Firmware <3.57	
<a href="#">1095627</a>	FL SWITCH 2208C	Firmware <3.57	
<a href="#">2702907</a>	FL SWITCH 2212-2TC-2SFX	Firmware <3.57	
<a href="#">2702905</a>	FL SWITCH 2214-2FX	Firmware <3.57	
<a href="#">2702906</a>	FL SWITCH 2214-2FX SM	Firmware <3.57	
<a href="#">1006188</a>	FL SWITCH 2214-2SFX	Firmware <3.57	
<a href="#">1044030</a>	FL SWITCH 2214-2SFX PN	Firmware <3.57	
<a href="#">2702904</a>	FL SWITCH 2216	Firmware <3.57	
<a href="#">1044029</a>	FL SWITCH 2216 PN	Firmware <3.57	
<a href="#">1278397</a>	FL SWITCH 2303-8SP1	Firmware <3.57	
<a href="#">2702653</a>	FL SWITCH 2304-2GC-2SFP	Firmware <3.57	
<a href="#">2702970</a>	FL SWITCH 2306-2SFP	Firmware <3.57	
<a href="#">1009222</a>	FL SWITCH 2306-2SFP PN	Firmware <3.57	
<a href="#">2702652</a>	FL SWITCH 2308	Firmware <3.57	
<a href="#">1009220</a>	FL SWITCH 2308 PN	Firmware <3.57	
<a href="#">2702910</a>	FL SWITCH 2312-2GC-2SFP	Firmware <3.57	
<a href="#">1006191</a>	FL SWITCH 2314-2SFP	Firmware <3.57	
<a href="#">1031683</a>	FL SWITCH 2314-2SFP PN	Firmware <3.57	
<a href="#">2702909</a>	FL SWITCH 2316	Firmware <3.57	
<a href="#">1031673</a>	FL SWITCH 2316 PN	Firmware <3.57	
<a href="#">1184084</a>	FL SWITCH 2316/K1	Firmware <3.57	
<a href="#">1088853</a>	FL SWITCH 2404-2TC-2SFX	Firmware <3.57	
<a href="#">1043414</a>	FL SWITCH 2406-2SFX	Firmware <3.57	
<a href="#">1089126</a>	FL SWITCH 2406-2SFX PN	Firmware <3.57	

Article	Name	Affected	Fixed
<a href="#">1043412</a>	FL SWITCH 2408	Firmware <3.57	
<a href="#">1089133</a>	FL SWITCH 2408 PN	Firmware <3.57	
<a href="#">1088875</a>	FL SWITCH 2412-2TC-2SFX	Firmware <3.57	
<a href="#">1043423</a>	FL SWITCH 2414-2SFX	Firmware <3.57	
<a href="#">1089139</a>	FL SWITCH 2414-2SFX PN	Firmware <3.57	
<a href="#">1043416</a>	FL SWITCH 2416	Firmware <3.57	
<a href="#">1089150</a>	FL SWITCH 2416 PN	Firmware <3.57	
<a href="#">1088872</a>	FL SWITCH 2504-2GC-2SFP	Firmware <3.57	
<a href="#">1043491</a>	FL SWITCH 2506-2SFP	Firmware <3.57	
<a href="#">1089135</a>	FL SWITCH 2506-2SFP PN	Firmware <3.57	
<a href="#">1215329</a>	FL SWITCH 2506-2SFP/K1	Firmware <3.57	
<a href="#">1043484</a>	FL SWITCH 2508	Firmware <3.57	
<a href="#">1089134</a>	FL SWITCH 2508 PN	Firmware <3.57	
<a href="#">1215350</a>	FL SWITCH 2508/K1	Firmware <3.57	
<a href="#">1088856</a>	FL SWITCH 2512-2GC-2SFP	Firmware <3.57	
<a href="#">1043499</a>	FL SWITCH 2514-2SFP	Firmware <3.57	
<a href="#">1089154</a>	FL SWITCH 2514-2SFP PN	Firmware <3.57	
<a href="#">1043496</a>	FL SWITCH 2516	Firmware <3.57	
<a href="#">1089205</a>	FL SWITCH 2516 PN	Firmware <3.57	
<a href="#">1106500</a>	FL SWITCH 2608	Firmware <3.57	
<a href="#">1106616</a>	FL SWITCH 2608 PN	Firmware <3.57	
<a href="#">1106615</a>	FL SWITCH 2708	Firmware <3.57	
<a href="#">1106610</a>	FL SWITCH 2708 PN	Firmware <3.57	
<a href="#">2702881</a>	FL NAT 2008	Firmware <3.57	
<a href="#">2702882</a>	FL NAT 2208	Firmware <3.57	
<a href="#">2702981</a>	FL NAT 2304-2GC-2SFP	Firmware <3.57	
<a href="#">1232304</a>	FL SWITCH TSN 2316	Firmware <3.57	
<a href="#">1232305</a>	FL SWITCH TSN 2312-2GC-2SFP	Firmware <3.57	
<a href="#">1232302</a>	FL SWITCH TSN 2314-2SFP	Firmware <3.57	
<a href="#">1525945</a>	FL SWITCH 5924-4GC	Firmware <3.57	
<a href="#">1525942</a>	FL SWITCH 5916-8GC-4SFP+	Firmware <3.57	
<a href="#">1525944</a>	FL SWITCH 5924SFP-4GC	Firmware <3.57	
<a href="#">1525939</a>	FL SWITCH 5924-4SFP+	Firmware <3.57	
<a href="#">1525943</a>	FL SWITCH 5916SFP-8GC-4SFP+	Firmware <3.57	

Article	Name	Affected	Fixed
<a href="#">2702992</a>	FL WLAN 1020	Firmware <26.06.00	
<a href="#">1386091</a>	FL WLAN 1120	Firmware <26.06.00	
<a href="#">1752493</a>	FL WLAN 1022	Firmware <26.06.00	
<a href="#">1752496</a>	FL WLAN 1122	Firmware <26.06.00	
<a href="#">1386092</a>	FL WLAN 1121	Firmware <26.06.00	
<a href="#">2702993</a>	FL WLAN 1021	Firmware <26.06.00	
<a href="#">1360276</a>	FL WLAN 2331	Firmware <26.06.00	
<a href="#">1510249</a>	FL WLAN 2341	Firmware <26.06.00	
<a href="#">1360275</a>	FL WLAN 2330	Firmware <26.06.00	
<a href="#">1510147</a>	FL WLAN 2340	Firmware <26.06.00	
<a href="#">2702528</a>	TC ROUTER 3002T-4G	Firmware <3.8.9	Firmware 3.8.9
<a href="#">1632697</a>	TC ROUTER 3002T-4G GL	Firmware <3.8.9	Firmware 3.8.9
<a href="#">1439475</a>	TC ROUTER 5004T-5G EU	Firmware <1.6.24	Firmware 1.6.24
<a href="#">1221706</a>	CLOUD CLIENT 1101T-TX/TX	Firmware <3.7.8	Firmware 3.7.8
<a href="#">2702885</a>	TC CLOUD CLIENT 1002-TX/TX	Firmware <3.7.8	Firmware 3.7.8
<a href="#">2702886</a>	TC CLOUD CLIENT 1002-4G	Firmware <3.8.9	Firmware 3.8.9
<a href="#">2702887</a>	TC CLOUD CLIENT 1002-4G VZW	Firmware <3.8.9	Firmware 3.8.9
<a href="#">2702888</a>	TC CLOUD CLIENT 1002-4G ATT	Firmware <3.8.9	Firmware 3.8.9
<a href="#">2702530</a>	TC ROUTER 2002T-4G	Firmware <3.8.9	Firmware 3.8.9
<a href="#">2702529</a>	TC ROUTER 3002T-3G	Firmware <3.8.9	Firmware 3.8.9
<a href="#">2702531</a>	TC ROUTER 2002T-3G	Firmware <3.8.9	Firmware 3.8.9
<a href="#">2702532</a>	TC ROUTER 3002T-4G VZW	Firmware <3.8.9	Firmware 3.8.9
<a href="#">2702533</a>	TC ROUTER 3002T-4G ATT	Firmware <3.8.9	Firmware 3.8.9
<a href="#">1234352</a>	TC ROUTER 4002T-4G EU	Firmware <5.0.72.102	
<a href="#">1234353</a>	TC ROUTER 4102T-4G EU WLAN	Firmware <5.0.72.102	
<a href="#">1234354</a>	TC ROUTER 4202T-4G EU WLAN	Firmware <5.0.72.102	
<a href="#">1107132</a>	FL TIMESERVER NTP	Firmware <5.0.71.101	
<a href="#">1503433</a>	CELLULINK 2401-4G EU M25	Firmware <2025.6.3	Firmware 2025.6.3
<a href="#">1503487</a>	CELLULINK 2401-4G EU M40	Firmware <2025.6.3	Firmware 2025.6.3
<a href="#">1637527</a>	CELLULINK 4401-4G GL M25	Firmware <2025.6.3	Firmware 2025.6.3
<a href="#">1637627</a>	CELLULINK 4401-4G GL M40	Firmware <2025.6.3	Firmware 2025.6.3
	OpenSSL 3.0.0	OpenSSL 3.0.0	
	OpenSSL 3.0.18	OpenSSL 3.0.18	
	OpenSSL 3.0.19		OpenSSL 3.0.19

## Acknowledgments

Phoenix Contact GmbH & Co. KG thanks the following parties for their efforts:

- CERT@VDE for coordination (see: <https://certvde.com>)

## Phoenix Contact GmbH & Co. KG

Namespace: <https://phoenixcontact.com/psirt>

[psirt@phoenixcontact.com](mailto:psirt@phoenixcontact.com)

## References

- PCSA-2026-00001 (EXTERNAL): <https://phoenixcontact.com/psirt>
- Phoenix Contact advisory overview at CERT@VDE (EXTERNAL): <https://certvde.com/de/advisories/vendor/phoenixcontact>
- VDE-2026-023: Phoenix Contact: Several products are affected by vulnerabilities found in OpenSSL - HTML (SELF): <https://certvde.com/en/advisories/VDE-2026-023>
- VDE-2026-023: Phoenix Contact: Several products are affected by vulnerabilities found in OpenSSL - CSAF (SELF): <https://phoenixcontact.csaf-tp.certvde.com/well-known/csaf/white/2026/vde-2026-023.json>

## Revision history

Version	Date of the revision	Summary of the revision
1.0.0	Wed Apr 22 08:00:00 CEST 2026	Initial release.

## Sharing rules

TLP:WHITE

For the TLP version see <https://www.first.org/tlp/>

# Vulnerability Details

## OpenSSL CMS AEAD Stack Overflow Vulnerability (CVE-2025-15467)

### CVE Details

PBMAC1 parameters in PKCS#12 files are missing validation which can trigger a stack-based buffer overflow, invalid pointer or NULL pointer dereference during MAC verification.

### CVE Impact

The stack buffer overflow or NULL pointer dereference may cause a crash leading to Denial of Service for an application that parses untrusted PKCS#12 files. The buffer overflow may also potentially enable code execution depending on platform mitigations.

When verifying a PKCS#12 file that uses PBMAC1 for the MAC, the PBKDF2 salt and keylength parameters from the file are used without validation. If the value of keylength exceeds the size of the fixed stack buffer used for the derived key (64 bytes), the key derivation will overflow the buffer. The overflow length is attacker-controlled. Also, if the salt parameter is not an OCTET STRING type this can lead to invalid or NULL pointer dereference.

Exploiting this issue requires a user or application to process a maliciously crafted PKCS#12 file. It is uncommon to accept untrusted PKCS#12 files in applications as they are usually used to store private keys which are trusted by definition. For this reason the issue was assessed as Moderate severity.

### CVE Characterisation

This vulnerability can be used to upload a malicious firmware image from an untrusted source. In the device context, there are two deviations from the original CVSS assessment. An attacker must trick the authenticated user into uploading malicious firmware without checking the SHA256 checksum (UI:R). The firmware upload function is only available to users with high privileges (PR:H).

### CVE Description

Issue summary: Parsing CMS AuthEnvelopedData message with maliciously crafted AEAD parameters can trigger a stack buffer overflow. Impact summary: A stack buffer overflow may lead to a crash, causing Denial of Service, or potentially remote code execution. When parsing CMS AuthEnvelopedData structures that use AEAD ciphers such as AES-GCM, the IV (Initialization Vector) encoded in the ASN.1 parameters is copied into a fixed-size stack buffer without verifying that its length fits the destination. An attacker can supply a crafted CMS message with an oversized IV, causing a stack-based out-of-bounds write before any authentication or tag verification occurs. Applications and services that parse untrusted CMS or PKCS#7 content using AEAD ciphers (e.g., S/MIME AuthEnvelopedData with AES-GCM) are vulnerable. Because the overflow occurs prior to authentication, no valid key material is required to trigger it. While exploitability to remote code execution depends on platform and toolchain mitigations, the stack-based write primitive represents a severe risk. The FIPS modules in 3.6, 3.5, 3.4, 3.3 and 3.0 are not affected by this issue, as the CMS implementation is outside the OpenSSL FIPS module boundary. OpenSSL 3.6, 3.5, 3.4, 3.3 and 3.0 are vulnerable to this issue. OpenSSL 1.1.1 and 1.0.2 are not affected by this issue.

**CWE:** CWE-787: Out-of-bounds Write

---

## Product status

### Known affected

Product	CVSS-Vector	CVSS Base Score
Firmware <1.9.0 installed on CHARX SEC-3150 Order number: 1138965	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <1.9.0 installed on CHARX SEC-3100 Order number: 1139012	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <1.9.0 installed on CHARX SEC-3050 Order number: 1139018	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <1.9.0 installed on CHARX SEC-3000 Order number: 1139022	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <2024.0.17 installed on AXC F 1152 Order number: 1151412	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <2024.0.17 installed on AXC F 2152 Order number: 2404267	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <2024.0.17 installed on GTC F 2172 Order number: 1079808	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <2024.0.17 installed on AXC F 3152 Order number: 1069208	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <2024.0.17 installed on RFC 4072S Order number: 1051328	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <2024.0.17 installed on NFC 482S Order number: 1050841	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <2024.0.17 installed on BPC 9102S Order number: 1246285	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <2024.0.17 installed on RFC 4072R Order number: 1136419	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <2026.0.0 installed on AXC F 2000 EA Order number: 1551772	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <V04.27.00.00 installed on Energy AXC PU Order number: 1264327	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <V01.11.00.00 installed on SMART RTU AXC SG Order number: 1110435	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <V01.04.00.00 installed on SMART RTU AXC IG Order number: 1264328	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <1.12.4 installed on ILC 2050 BI Order number: 2403160	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <1.12.3 installed on ILC 2050 BI-L Order number: 2404671	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <1.12.3 installed on ILC 2250 BI Order number: 1541303	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <1.12.3 installed on ILC 2250 BI-L Order number: 1535543	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <1.12.3 installed on CATAN C1 EN Order number: 1371432	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <10.6.1 installed on FL MGuard 2102 Order number: 1357828	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <10.6.1 installed on FL MGuard 2105 Order number: 1357850	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <10.6.1 installed on FL MGuard 4302 Order number: 1357840	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8

Product	CVSS-Vector	CVSS Base Score
Firmware <10.6.1 installed on FL MGuard 4305 Order number: 1357875	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <10.6.1 installed on FL MGuard 4102 PCIE Order number: 1357842	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <10.6.1 installed on FL MGuard 4102 PCI Order number: 1441187	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <10.6.1 installed on FL MGuard 4302/K1 Order number: 1488318	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <10.6.1 installed on FL MGuard 4102 PCIE/K2 Order number: 1427378	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <10.6.1 installed on FL MGuard 4102 PCI/K2 Order number: 1488314	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <10.6.1 installed on FL MGuard 4302/K2 Order number: 1427379	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <10.6.1 installed on FL MGuard 4302/K3 Order number: 1488325	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <10.6.1 installed on FL MGuard 4302/K4 Order number: 1488326	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <10.6.1 installed on FL MGuard 4302/KX Order number: 1696708	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <10.6.1 installed on FL MGuard 4305/KX Order number: 1696779	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2005 Order number: 2702323	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2008 Order number: 2702324	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2008F Order number: 1106707	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2016 Order number: 2702903	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2105 Order number: 2702665	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2108 Order number: 2702666	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2116 Order number: 2702908	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2204-2TC-2SFX Order number: 2702334	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2205 Order number: 2702326	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2206-2FX Order number: 2702330	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2206-2FX SM Order number: 2702331	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2206-2FX SM ST Order number: 2702333	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2206-2FX ST Order number: 2702332	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8

Product	CVSS-Vector	CVSS Base Score
Firmware <3.57 installed on FL SWITCH 2206-2SFX Order number: 2702969	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2206-2SFX PN Order number: 1044028	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2206C-2FX Order number: 1095628	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2207-FX Order number: 2702328	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2207-FX SM Order number: 2702329	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2208 Order number: 2702327	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2208 PN Order number: 1044024	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2208C Order number: 1095627	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2212-2TC-2SFX Order number: 2702907	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2214-2FX Order number: 2702905	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2214-2FX SM Order number: 2702906	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2214-2SFX Order number: 1006188	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2214-2SFX PN Order number: 1044030	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2216 Order number: 2702904	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2216 PN Order number: 1044029	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2303-8SP1 Order number: 1278397	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2304-2GC-2SFP Order number: 2702653	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2306-2SFP Order number: 2702970	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2306-2SFP PN Order number: 1009222	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2308 Order number: 2702652	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2308 PN Order number: 1009220	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2312-2GC-2SFP Order number: 2702910	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2314-2SFP Order number: 1006191	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2314-2SFP PN Order number: 1031683	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8

Product	CVSS-Vector	CVSS Base Score
Firmware <3.57 installed on FL SWITCH 2316 Order number: 2702909	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2316 PN Order number: 1031673	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2316/K1 Order number: 1184084	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2404-2TC-2SFX Order number: 1088853	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2406-2SFX Order number: 1043414	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2406-2SFX PN Order number: 1089126	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2408 Order number: 1043412	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2408 PN Order number: 1089133	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2412-2TC-2SFX Order number: 1088875	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2414-2SFX Order number: 1043423	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2414-2SFX PN Order number: 1089139	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2416 Order number: 1043416	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2416 PN Order number: 1089150	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2504-2GC-2SFP Order number: 1088872	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2506-2SFP Order number: 1043491	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2506-2SFP PN Order number: 1089135	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2506-2SFP/K1 Order number: 1215329	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2508 Order number: 1043484	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2508 PN Order number: 1089134	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2508/K1 Order number: 1215350	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2512-2GC-2SFP Order number: 1088856	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2514-2SFP Order number: 1043499	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2514-2SFP PN Order number: 1089154	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2516 Order number: 1043496	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8

Product	CVSS-Vector	CVSS Base Score
Firmware <3.57 installed on FL SWITCH 2516 PN Order number: 1089205	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2608 Order number: 1106500	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2608 PN Order number: 1106616	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2708 Order number: 1106615	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 2708 PN Order number: 1106610	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL NAT 2008 Order number: 2702881	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL NAT 2208 Order number: 2702882	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL NAT 2304-2GC-2SFP Order number: 2702981	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH TSN 2316 Order number: 1232304	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH TSN 2312-2GC-2SFP Order number: 1232305	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH TSN 2314-2SFP Order number: 1232302	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 5924-4GC Order number: 1525945	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 5916-8GC-4SFP+ Order number: 1525942	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 5924SFP-4GC Order number: 1525944	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 5924-4SFP+ Order number: 1525939	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.57 installed on FL SWITCH 5916SFP-8GC-4SFP+ Order number: 1525943	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <26.06.00 installed on FL WLAN 1020 Order number: 2702992	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <26.06.00 installed on FL WLAN 1120 Order number: 1386091	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <26.06.00 installed on FL WLAN 1022 Order number: 1752493	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <26.06.00 installed on FL WLAN 1122 Order number: 1752496	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <26.06.00 installed on FL WLAN 1121 Order number: 1386092	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <26.06.00 installed on FL WLAN 1021 Order number: 2702993	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <26.06.00 installed on FL WLAN 2331 Order number: 1360276	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <26.06.00 installed on FL WLAN 2341 Order number: 1510249	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8

Product	CVSS-Vector	CVSS Base Score
Firmware <26.06.00 installed on FL WLAN 2330 Order number: 1360275	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <26.06.00 installed on FL WLAN 2340 Order number: 1510147	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.8.9 installed on TC ROUTER 3002T-4G Order number: 2702528	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.8.9 installed on TC ROUTER 3002T-4G GL Order number: 1632697	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <1.6.24 installed on TC ROUTER 5004T-5G EU Order number: 1439475	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.7.8 installed on CLOUD CLIENT 1101T-TX/TX Order number: 1221706	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.7.8 installed on TC CLOUD CLIENT 1002-TX/TX Order number: 2702885	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.8.9 installed on TC CLOUD CLIENT 1002-4G Order number: 2702886	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.8.9 installed on TC CLOUD CLIENT 1002-4G VZW Order number: 2702887	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.8.9 installed on TC CLOUD CLIENT 1002-4G ATT Order number: 2702888	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.8.9 installed on TC ROUTER 2002T-4G Order number: 2702530	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.8.9 installed on TC ROUTER 3002T-3G Order number: 2702529	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.8.9 installed on TC ROUTER 2002T-3G Order number: 2702531	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.8.9 installed on TC ROUTER 3002T-4G VZW Order number: 2702532	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <3.8.9 installed on TC ROUTER 3002T-4G ATT Order number: 2702533	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <5.0.72.102 installed on TC ROUTER 4002T-4G EU Order number: 1234352	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <5.0.72.102 installed on TC ROUTER 4102T-4G EU WLAN Order number: 1234353	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <5.0.72.102 installed on TC ROUTER 4202T-4G EU WLAN Order number: 1234354	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <5.0.71.101 installed on FL TIMESERVER NTP Order number: 1107132	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <2025.6.3 installed on CELLULINK 2401-4G EU M25 Order number: 1503433	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <2025.6.3 installed on CELLULINK 2401-4G EU M40 Order number: 1503487	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <2025.6.3 installed on CELLULINK 4401-4G GL M25 Order number: 1637527	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8
Firmware <2025.6.3 installed on CELLULINK 4401-4G GL M40 Order number: 1637627	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H	8.8

Product	CVSS-Vector	CVSS Base Score
OpenSSL 3.0.0	CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H	9.8
OpenSSL 3.0.18	CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H	9.8

### First affected

Product	CVSS-Vector	CVSS Base Score
OpenSSL 3.0.0	CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H	9.8

### Last affected

Product	CVSS-Vector	CVSS Base Score
OpenSSL 3.0.18	CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H	9.8

### Fixed

Product
1.9.0 installed on CHARX SEC-3150 Order number: 1138965 ( <a href="#">Download</a> )
1.9.0 installed on CHARX SEC-3100 Order number: 1139012 ( <a href="#">Download</a> )
1.9.0 installed on CHARX SEC-3050 Order number: 1139018 ( <a href="#">Download</a> )
1.9.0 installed on CHARX SEC-3000 Order number: 1139022 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on AXC F 1152 Order number: 1151412 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on AXC F 2152 Order number: 2404267 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on GTC F 2172 Order number: 1079808 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on AXC F 3152 Order number: 1069208 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on RFC 4072S Order number: 1051328 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on NFC 482S Order number: 1050841 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on BPC 9102S Order number: 1246285 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on RFC 4072R Order number: 1136419 ( <a href="#">Download</a> )
Firmware 2026.0.0 installed on AXC F 2000 EA Order number: 1551772 ( <a href="#">Download</a> )
Firmware 10.6.1 installed on FL MGuard 2102 Order number: 1357828 ( <a href="#">Download</a> )

---

**Product**

---

Firmware 10.6.1 installed on FL MGuard 2105  
Order number: 1357850 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4302  
Order number: 1357840 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4305  
Order number: 1357875 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4102 PCIE  
Order number: 1357842 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4102 PCI  
Order number: 1441187 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4302/K1  
Order number: 1488318 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4102 PCIE/K2  
Order number: 1427378 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4102 PCI/K2  
Order number: 1488314 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4302/K2  
Order number: 1427379 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4302/K3  
Order number: 1488325 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4302/K4  
Order number: 1488326 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4302/KX  
Order number: 1696708 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4305/KX  
Order number: 1696779 ([Download](#))

---

Firmware 3.8.9 installed on TC Router 3002T-4G  
Order number: 2702528 ([Download](#))

---

Firmware 3.8.9 installed on TC Router 3002T-4G GL  
Order number: 1632697 ([Download](#))

---

Firmware 1.6.24 installed on TC Router 5004T-5G EU  
Order number: 1439475 ([Download](#))

---

Firmware 3.7.8 installed on Cloud Client 1101T-TX/TX  
Order number: 1221706 ([Download](#))

---

Firmware 3.7.8 installed on TC Cloud Client 1002-TX/TX  
Order number: 2702885 ([Download](#))

---

Firmware 3.8.9 installed on TC Cloud Client 1002-4G  
Order number: 2702886 ([Download](#))

---

Firmware 3.8.9 installed on TC Cloud Client 1002-4G VZW  
Order number: 2702887 ([Download](#))

---

Firmware 3.8.9 installed on TC Cloud Client 1002-4G ATT  
Order number: 2702888 ([Download](#))

---

Firmware 3.8.9 installed on TC Router 2002T-4G  
Order number: 2702530 ([Download](#))

---

Firmware 3.8.9 installed on TC Router 3002T-3G  
Order number: 2702529 ([Download](#))

---

Firmware 3.8.9 installed on TC Router 2002T-3G  
Order number: 2702531 ([Download](#))

---

**Product**

---

Firmware 3.8.9 installed on TC ROUTER 3002T-4G VZW  
Order number: 2702532 ([Download](#))

---

Firmware 3.8.9 installed on TC ROUTER 3002T-4G ATT  
Order number: 2702533 ([Download](#))

---

Firmware 2025.6.3 installed on CELLULINK 2401-4G EU M25  
Order number: 1503433 ([Download](#))

---

Firmware 2025.6.3 installed on CELLULINK 2401-4G EU M40  
Order number: 1503487 ([Download](#))

---

Firmware 2025.6.3 installed on CELLULINK 4401-4G GL M25  
Order number: 1637527 ([Download](#))

---

Firmware 2025.6.3 installed on CELLULINK 4401-4G GL M40  
Order number: 1637627 ([Download](#))

---

OpenSSL 3.0.19

---

**Under investigation****Product**

---

Firmware V04.27.00.00 installed on Energy AXC PU  
Order number: 1264327

---

Firmware V01.11.00.00 installed on SMART RTU AXC SG  
Order number: 1110435

---

Firmware V01.04.00.00 installed on SMART RTU AXC IG  
Order number: 1264328

---

Firmware 1.12.4 installed on ILC 2050 BI  
Order number: 2403160

---

Firmware 1.12.4 installed on ILC 2050 BI-L  
Order number: 2404671

---

Firmware 1.12.3 installed on ILC 2250 BI  
Order number: 1541303

---

Firmware 1.12.3 installed on ILC 2250 BI-L  
Order number: 1535543

---

Firmware 1.12.3 installed on CATAN C1 EN  
Order number: 1371432

---

Firmware 3.57 installed on FL SWITCH 2005  
Order number: 2702323

---

Firmware 3.57 installed on FL SWITCH 2008  
Order number: 2702324

---

Firmware 3.57 installed on FL SWITCH 2008F  
Order number: 1106707

---

Firmware 3.57 installed on FL SWITCH 2016  
Order number: 2702903

---

Firmware 3.57 installed on FL SWITCH 2105  
Order number: 2702665

---

Firmware 3.57 installed on FL SWITCH 2108  
Order number: 2702666

---

Firmware 3.57 installed on FL SWITCH 2116  
Order number: 2702908

---

Firmware 3.57 installed on FL SWITCH 2204-2TC-2SFX  
Order number: 2702334

---

---

**Product**

---

Firmware 3.57 installed on FL SWITCH 2205  
Order number: 2702326

---

Firmware 3.57 installed on FL SWITCH 2206-2FX  
Order number: 2702330

---

Firmware 3.57 installed on FL SWITCH 2206-2FX SM  
Order number: 2702331

---

Firmware 3.57 installed on FL SWITCH 2206-2FX SM ST  
Order number: 2702333

---

Firmware 3.57 installed on FL SWITCH 2206-2FX ST  
Order number: 2702332

---

Firmware 3.57 installed on FL SWITCH 2206-2SFX  
Order number: 2702969

---

Firmware 3.57 installed on FL SWITCH 2206-2SFX PN  
Order number: 1044028

---

Firmware 3.57 installed on FL SWITCH 2206C-2FX  
Order number: 1095628

---

Firmware 3.57 installed on FL SWITCH 2207-FX  
Order number: 2702328

---

Firmware 3.57 installed on FL SWITCH 2207-FX SM  
Order number: 2702329

---

Firmware 3.57 installed on FL SWITCH 2208  
Order number: 2702327

---

Firmware 3.57 installed on FL SWITCH 2208 PN  
Order number: 1044024

---

Firmware 3.57 installed on FL SWITCH 2208C  
Order number: 1095627

---

Firmware 3.57 installed on FL SWITCH 2212-2TC-2SFX  
Order number: 2702907

---

Firmware 3.57 installed on FL SWITCH 2214-2FX  
Order number: 2702905

---

Firmware 3.57 installed on FL SWITCH 2214-2FX SM  
Order number: 2702906

---

Firmware 3.57 installed on FL SWITCH 2214-2SFX  
Order number: 1006188

---

Firmware 3.57 installed on FL SWITCH 2214-2SFX PN  
Order number: 1044030

---

Firmware 3.57 installed on FL SWITCH 2216  
Order number: 2702904

---

Firmware 3.57 installed on FL SWITCH 2216 PN  
Order number: 1044029

---

Firmware 3.57 installed on FL SWITCH 2303-8SP1  
Order number: 1278397

---

Firmware 3.57 installed on FL SWITCH 2304-2GC-2SFP  
Order number: 2702653

---

Firmware 3.57 installed on FL SWITCH 2306-2SFP  
Order number: 2702970

---

Firmware 3.57 installed on FL SWITCH 2306-2SFP PN  
Order number: 1009222

---

**Product**

---

Firmware 3.57 installed on FL SWITCH 2308  
Order number: 2702652

---

Firmware 3.57 installed on FL SWITCH 2308 PN  
Order number: 1009220

---

Firmware 3.57 installed on FL SWITCH 2312-2GC-2SFP  
Order number: 2702910

---

Firmware 3.57 installed on FL SWITCH 2314-2SFP  
Order number: 1006191

---

Firmware 3.57 installed on FL SWITCH 2314-2SFP PN  
Order number: 1031683

---

Firmware 3.57 installed on FL SWITCH 2316  
Order number: 2702909

---

Firmware 3.57 installed on FL SWITCH 2316 PN  
Order number: 1031673

---

Firmware 3.57 installed on FL SWITCH 2316/K1  
Order number: 1184084

---

Firmware 3.57 installed on FL SWITCH 2404-2TC-2SFX  
Order number: 1088853

---

Firmware 3.57 installed on FL SWITCH 2406-2SFX  
Order number: 1043414

---

Firmware 3.57 installed on FL SWITCH 2406-2SFX PN  
Order number: 1089126

---

Firmware 3.57 installed on FL SWITCH 2408  
Order number: 1043412

---

Firmware 3.57 installed on FL SWITCH 2408 PN  
Order number: 1089133

---

Firmware 3.57 installed on FL SWITCH 2412-2TC-2SFX  
Order number: 1088875

---

Firmware 3.57 installed on FL SWITCH 2414-2SFX  
Order number: 1043423

---

Firmware 3.57 installed on FL SWITCH 2414-2SFX PN  
Order number: 1089139

---

Firmware 3.57 installed on FL SWITCH 2416  
Order number: 1043416

---

Firmware 3.57 installed on FL SWITCH 2416 PN  
Order number: 1089150

---

Firmware 3.57 installed on FL SWITCH 2504-2GC-2SFP  
Order number: 1088872

---

Firmware 3.57 installed on FL SWITCH 2506-2SFP  
Order number: 1043491

---

Firmware 3.57 installed on FL SWITCH 2506-2SFP PN  
Order number: 1089135

---

Firmware 3.57 installed on FL SWITCH 2506-2SFP/K1  
Order number: 1215329

---

Firmware 3.57 installed on FL SWITCH 2508  
Order number: 1043484

---

Firmware 3.57 installed on FL SWITCH 2508 PN  
Order number: 1089134

---

**Product**

---

Firmware 3.57 installed on FL SWITCH 2508/K1  
Order number: 1215350

---

Firmware 3.57 installed on FL SWITCH 2512-2GC-2SFP  
Order number: 1088856

---

Firmware 3.57 installed on FL SWITCH 2514-2SFP  
Order number: 1043499

---

Firmware 3.57 installed on FL SWITCH 2514-2SFP PN  
Order number: 1089154

---

Firmware 3.57 installed on FL SWITCH 2516  
Order number: 1043496

---

Firmware 3.57 installed on FL SWITCH 2516 PN  
Order number: 1089205

---

Firmware 3.57 installed on FL SWITCH 2608  
Order number: 1106500

---

Firmware 3.57 installed on FL SWITCH 2608 PN  
Order number: 1106616

---

Firmware 3.57 installed on FL SWITCH 2708  
Order number: 1106615

---

Firmware 3.57 installed on FL SWITCH 2708 PN  
Order number: 1106610

---

Firmware 3.57 installed on FL NAT 2008  
Order number: 2702881

---

Firmware 3.57 installed on FL NAT 2208  
Order number: 2702882

---

Firmware 3.57 installed on FL NAT 2304-2GC-2SFP  
Order number: 2702981

---

Firmware 3.57 installed on FL SWITCH TSN 2316  
Order number: 1232304

---

Firmware 3.57 installed on FL SWITCH TSN 2312-2GC-2SFP  
Order number: 1232305

---

Firmware 3.57 installed on FL SWITCH TSN 2314-2SFP  
Order number: 1232302

---

Firmware 3.57 installed on FL SWITCH 5924-4GC  
Order number: 1525945

---

Firmware 3.57 installed on FL SWITCH 5916-8GC-4SFP+  
Order number: 1525942

---

Firmware 3.57 installed on FL SWITCH 5924SFP-4GC  
Order number: 1525944

---

Firmware 3.57 installed on FL SWITCH 5924-4SFP+  
Order number: 1525939

---

Firmware 3.57 installed on FL SWITCH 5916SFP-8GC-4SFP+  
Order number: 1525943

---

Firmware 26.06.00 installed on FL WLAN 1020  
Order number: 2702992

---

Firmware 26.06.00 installed on FL WLAN 1120  
Order number: 1386091

---

Firmware 26.06.00 installed on FL WLAN 1022  
Order number: 1752493

---

**Product**

---

Firmware 26.06.00 installed on FL WLAN 1122  
Order number: 1752496

---

Firmware 26.06.00 installed on FL WLAN 1121  
Order number: 1386092

---

Firmware 26.06.00 installed on FL WLAN 1021  
Order number: 2702993

---

Firmware 26.06.00 installed on FL WLAN 2331  
Order number: 1360276

---

Firmware 26.06.00 installed on FL WLAN 2341  
Order number: 1510249

---

Firmware 26.06.00 installed on FL WLAN 2330  
Order number: 1360275

---

Firmware 26.06.00 installed on FL WLAN 2340  
Order number: 1510147

---

Firmware 5.0.72.102 installed on TC ROUTER 4002T-4G EU  
Order number: 1234352

---

Firmware 5.0.72.102 installed on TC ROUTER 4102T-4G EU WLAN  
Order number: 1234353

---

Firmware 5.0.72.102 installed on TC ROUTER 4202T-4G EU WLAN  
Order number: 1234354

---

Firmware 5.0.71.101 installed on FL TIMESERVER NTP  
Order number: 1107132

---

## OpenSSL Calling PKCS12\_get\_friendlyname() function on a maliciously crafted PKCS#12 can trigger a one byte write before the allocated buffer. (CVE-2025-69419)

### CVE Details

PBMAC1 parameters in PKCS#12 files are missing validation which can trigger a stack-based buffer overflow, invalid pointer or NULL pointer dereference during MAC verification.

### CVE Impact

The stack buffer overflow or NULL pointer dereference may cause a crash leading to Denial of Service for an application that parses untrusted PKCS#12 files. The buffer overflow may also potentially enable code execution depending on platform mitigations.

### CVE Characterisation

In the device context, there is one deviation from the original CVSS assessment. The attacker must be logged in with an high privileged User (PR:H).

### CVE Description

Issue summary: Calling PKCS12\_get\_friendlyname() function on a maliciously crafted PKCS#12 file with a BMPString (UTF-16BE) friendly name containing non-ASCII BMP code point can trigger a one byte write before the allocated buffer. Impact summary: The out-of-bounds write can cause a memory corruption which can have various consequences including a Denial of Service. The OPENSSL\_uni2utf8() function performs a two-pass conversion of a PKCS#12 BMPString (UTF-16BE) to UTF-8. In the second pass, when emitting UTF-8 bytes, the helper function bmp\_to\_utf8() incorrectly forwards the remaining UTF-16 source byte count as the destination buffer capacity to UTF8\_putc(). For BMP code points above U+07FF,

UTF-8 requires three bytes, but the forwarded capacity can be just two bytes. UTF8\_putc() then returns -1, and this negative value is added to the output length without validation, causing the length to become negative. The subsequent trailing NUL byte is then written at a negative offset, causing write outside of heap allocated buffer. The vulnerability is reachable via the public PKCS12\_get\_friendlyname() API when parsing attacker-controlled PKCS#12 files. While PKCS12\_parse() uses a different code path that avoids this issue, PKCS12\_get\_friendlyname() directly invokes the vulnerable function. Exploitation requires an attacker to provide a malicious PKCS#12 file to be parsed by the application and the attacker can just trigger a one zero byte write before the allocated buffer. For that reason the issue was assessed as Low severity according to our Security Policy. The FIPS modules in 3.6, 3.5, 3.4, 3.3 and 3.0 are not affected by this issue, as the PKCS#12 implementation is outside the OpenSSL FIPS module boundary. OpenSSL 3.6, 3.5, 3.4, 3.3, 3.0 and 1.1.1 are vulnerable to this issue. OpenSSL 1.0.2 is not affected by this issue.

**CWE:** CWE-787: Out-of-bounds Write

## Product status

### Known affected

Product	CVSS-Vector	CVSS Base Score
Firmware <1.9.0 installed on CHARX SEC-3150 Order number: 1138965	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <1.9.0 installed on CHARX SEC-3100 Order number: 1139012	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <1.9.0 installed on CHARX SEC-3050 Order number: 1139018	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <1.9.0 installed on CHARX SEC-3000 Order number: 1139022	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <1.12.4 installed on ILC 2050 BI Order number: 2403160	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <1.12.3 installed on ILC 2050 BI-L Order number: 2404671	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <1.12.3 installed on ILC 2250 BI Order number: 1541303	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <1.12.3 installed on ILC 2250 BI-L Order number: 1535543	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <1.12.3 installed on CATAN C1 EN Order number: 1371432	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2005 Order number: 2702323	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2008 Order number: 2702324	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2008F Order number: 1106707	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2016 Order number: 2702903	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2105 Order number: 2702665	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2108 Order number: 2702666	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2116 Order number: 2702908	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9

Product	CVSS-Vector	CVSS Base Score
Firmware <3.57 installed on FL SWITCH 2204-2TC-2SFX Order number: 2702334	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2205 Order number: 2702326	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2206-2FX Order number: 2702330	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2206-2FX SM Order number: 2702331	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2206-2FX SM ST Order number: 2702333	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2206-2FX ST Order number: 2702332	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2206-2SFX Order number: 2702969	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2206-2SFX PN Order number: 1044028	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2206C-2FX Order number: 1095628	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2207-FX Order number: 2702328	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2207-FX SM Order number: 2702329	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2208 Order number: 2702327	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2208 PN Order number: 1044024	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2208C Order number: 1095627	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2212-2TC-2SFX Order number: 2702907	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2214-2FX Order number: 2702905	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2214-2FX SM Order number: 2702906	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2214-2SFX Order number: 1006188	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2214-2SFX PN Order number: 1044030	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2216 Order number: 2702904	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2216 PN Order number: 1044029	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2303-8SP1 Order number: 1278397	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2304-2GC-2SFP Order number: 2702653	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2306-2SFP Order number: 2702970	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9

Product	CVSS-Vector	CVSS Base Score
Firmware <3.57 installed on FL SWITCH 2306-2SFP PN Order number: 1009222	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2308 Order number: 2702652	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2308 PN Order number: 1009220	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2312-2GC-2SFP Order number: 2702910	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2314-2SFP Order number: 1006191	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2314-2SFP PN Order number: 1031683	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2316 Order number: 2702909	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2316 PN Order number: 1031673	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2316/K1 Order number: 1184084	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2404-2TC-2SFX Order number: 1088853	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2406-2SFX Order number: 1043414	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2406-2SFX PN Order number: 1089126	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2408 Order number: 1043412	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2408 PN Order number: 1089133	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2412-2TC-2SFX Order number: 1088875	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2414-2SFX Order number: 1043423	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2414-2SFX PN Order number: 1089139	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2416 Order number: 1043416	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2416 PN Order number: 1089150	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2504-2GC-2SFP Order number: 1088872	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2506-2SFP Order number: 1043491	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2506-2SFP PN Order number: 1089135	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2506-2SFP/K1 Order number: 1215329	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2508 Order number: 1043484	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9

Product	CVSS-Vector	CVSS Base Score
Firmware <3.57 installed on FL SWITCH 2508 PN Order number: 1089134	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2508/K1 Order number: 1215350	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2512-2GC-2SFP Order number: 1088856	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2514-2SFP Order number: 1043499	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2514-2SFP PN Order number: 1089154	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2516 Order number: 1043496	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2516 PN Order number: 1089205	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2608 Order number: 1106500	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2608 PN Order number: 1106616	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2708 Order number: 1106615	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 2708 PN Order number: 1106610	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL NAT 2008 Order number: 2702881	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL NAT 2208 Order number: 2702882	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL NAT 2304-2GC-2SFP Order number: 2702981	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH TSN 2316 Order number: 1232304	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH TSN 2312-2GC-2SFP Order number: 1232305	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH TSN 2314-2SFP Order number: 1232302	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 5924-4GC Order number: 1525945	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 5916-8GC-4SFP+ Order number: 1525942	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 5924SFP-4GC Order number: 1525944	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 5924-4SFP+ Order number: 1525939	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.57 installed on FL SWITCH 5916SFP-8GC-4SFP+ Order number: 1525943	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <26.06.00 installed on FL WLAN 1020 Order number: 2702992	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <26.06.00 installed on FL WLAN 1120 Order number: 1386091	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9

Product	CVSS-Vector	CVSS Base Score
Firmware <26.06.00 installed on FL WLAN 1022 Order number: 1752493	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <26.06.00 installed on FL WLAN 1122 Order number: 1752496	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <26.06.00 installed on FL WLAN 1121 Order number: 1386092	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <26.06.00 installed on FL WLAN 1021 Order number: 2702993	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.8.9 installed on TC ROUTER 3002T-4G Order number: 2702528	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.8.9 installed on TC ROUTER 3002T-4G GL Order number: 1632697	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <1.6.24 installed on TC ROUTER 5004T-5G EU Order number: 1439475	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.7.8 installed on CLOUD CLIENT 1101T-TX/TX Order number: 1221706	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.7.8 installed on TC CLOUD CLIENT 1002-TX/TX Order number: 2702885	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.8.9 installed on TC CLOUD CLIENT 1002-4G Order number: 2702886	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.8.9 installed on TC CLOUD CLIENT 1002-4G VZW Order number: 2702887	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.8.9 installed on TC CLOUD CLIENT 1002-4G ATT Order number: 2702888	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.8.9 installed on TC ROUTER 2002T-4G Order number: 2702530	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.8.9 installed on TC ROUTER 3002T-3G Order number: 2702529	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.8.9 installed on TC ROUTER 2002T-3G Order number: 2702531	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.8.9 installed on TC ROUTER 3002T-4G VZW Order number: 2702532	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <3.8.9 installed on TC ROUTER 3002T-4G ATT Order number: 2702533	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <5.0.72.102 installed on TC ROUTER 4002T-4G EU Order number: 1234352	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <5.0.72.102 installed on TC ROUTER 4102T-4G EU WLAN Order number: 1234353	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <5.0.72.102 installed on TC ROUTER 4202T-4G EU WLAN Order number: 1234354	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
Firmware <5.0.71.101 installed on FL TIMESERVER NTP Order number: 1107132	CVSS:3.1/AV:N/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:N	5.9
OpenSSL 3.0.0	CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:H/I:H/A:N	7.4
OpenSSL 3.0.18	CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:H/I:H/A:N	7.4

## First affected

Product	CVSS-Vector	CVSS Base Score
OpenSSL 3.0.0	CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:H/I:H/A:N	7.4

## Last affected

Product	CVSS-Vector	CVSS Base Score
OpenSSL 3.0.18	CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:H/I:H/A:N	7.4

## Fixed

Product
1.9.0 installed on CHARX SEC-3150 Order number: 1138965 ( <a href="#">Download</a> )
1.9.0 installed on CHARX SEC-3100 Order number: 1139012 ( <a href="#">Download</a> )
1.9.0 installed on CHARX SEC-3050 Order number: 1139018 ( <a href="#">Download</a> )
1.9.0 installed on CHARX SEC-3000 Order number: 1139022 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on AXC F 1152 Order number: 1151412 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on AXC F 2152 Order number: 2404267 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on GTC F 2172 Order number: 1079808 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on AXC F 3152 Order number: 1069208 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on RFC 4072S Order number: 1051328 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on NFC 482S Order number: 1050841 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on BPC 9102S Order number: 1246285 ( <a href="#">Download</a> )
Firmware 2024.0.17 installed on RFC 4072R Order number: 1136419 ( <a href="#">Download</a> )
Firmware 2026.0.0 installed on AXC F 2000 EA Order number: 1551772 ( <a href="#">Download</a> )
Firmware 10.6.1 installed on FL MGUARD 2102 Order number: 1357828 ( <a href="#">Download</a> )
Firmware 10.6.1 installed on FL MGUARD 2105 Order number: 1357850 ( <a href="#">Download</a> )
Firmware 10.6.1 installed on FL MGUARD 4302 Order number: 1357840 ( <a href="#">Download</a> )
Firmware 10.6.1 installed on FL MGUARD 4305 Order number: 1357875 ( <a href="#">Download</a> )

---

**Product**

---

Firmware 10.6.1 installed on FL MGuard 4102 PCIE  
Order number: 1357842 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4102 PCI  
Order number: 1441187 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4302/K1  
Order number: 1488318 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4102 PCIE/K2  
Order number: 1427378 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4102 PCI/K2  
Order number: 1488314 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4302/K2  
Order number: 1427379 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4302/K3  
Order number: 1488325 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4302/K4  
Order number: 1488326 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4302/KX  
Order number: 1696708 ([Download](#))

---

Firmware 10.6.1 installed on FL MGuard 4305/KX  
Order number: 1696779 ([Download](#))

---

Firmware 3.8.9 installed on TC Router 3002T-4G  
Order number: 2702528 ([Download](#))

---

Firmware 3.8.9 installed on TC Router 3002T-4G GL  
Order number: 1632697 ([Download](#))

---

Firmware 1.6.24 installed on TC Router 5004T-5G EU  
Order number: 1439475 ([Download](#))

---

Firmware 3.7.8 installed on Cloud Client 1101T-TX/TX  
Order number: 1221706 ([Download](#))

---

Firmware 3.7.8 installed on TC Cloud Client 1002-TX/TX  
Order number: 2702885 ([Download](#))

---

Firmware 3.8.9 installed on TC Cloud Client 1002-4G  
Order number: 2702886 ([Download](#))

---

Firmware 3.8.9 installed on TC Cloud Client 1002-4G VZW  
Order number: 2702887 ([Download](#))

---

Firmware 3.8.9 installed on TC Cloud Client 1002-4G ATT  
Order number: 2702888 ([Download](#))

---

Firmware 3.8.9 installed on TC Router 2002T-4G  
Order number: 2702530 ([Download](#))

---

Firmware 3.8.9 installed on TC Router 3002T-3G  
Order number: 2702529 ([Download](#))

---

Firmware 3.8.9 installed on TC Router 2002T-3G  
Order number: 2702531 ([Download](#))

---

Firmware 3.8.9 installed on TC Router 3002T-4G VZW  
Order number: 2702532 ([Download](#))

---

Firmware 3.8.9 installed on TC Router 3002T-4G ATT  
Order number: 2702533 ([Download](#))

---

Firmware 2025.6.3 installed on Cellulink 2401-4G EU M25  
Order number: 1503433 ([Download](#))

---

**Product**

---

Firmware 2025.6.3 installed on CELLULINK 2401-4G EU M40  
Order number: 1503487 ([Download](#))

---

Firmware 2025.6.3 installed on CELLULINK 4401-4G GL M25  
Order number: 1637527 ([Download](#))

---

Firmware 2025.6.3 installed on CELLULINK 4401-4G GL M40  
Order number: 1637627 ([Download](#))

---

OpenSSL 3.0.19

---

**Under investigation****Product**

---

Firmware V04.27.00.00 installed on Energy AXC PU  
Order number: 1264327

---

Firmware V01.11.00.00 installed on SMART RTU AXC SG  
Order number: 1110435

---

Firmware V01.04.00.00 installed on SMART RTU AXC IG  
Order number: 1264328

---

Firmware 1.12.4 installed on ILC 2050 BI  
Order number: 2403160

---

Firmware 1.12.4 installed on ILC 2050 BI-L  
Order number: 2404671

---

Firmware 1.12.3 installed on ILC 2250 BI  
Order number: 1541303

---

Firmware 1.12.3 installed on ILC 2250 BI-L  
Order number: 1535543

---

Firmware 1.12.3 installed on CATAN C1 EN  
Order number: 1371432

---

Firmware 3.57 installed on FL SWITCH 2005  
Order number: 2702323

---

Firmware 3.57 installed on FL SWITCH 2008  
Order number: 2702324

---

Firmware 3.57 installed on FL SWITCH 2008F  
Order number: 1106707

---

Firmware 3.57 installed on FL SWITCH 2016  
Order number: 2702903

---

Firmware 3.57 installed on FL SWITCH 2105  
Order number: 2702665

---

Firmware 3.57 installed on FL SWITCH 2108  
Order number: 2702666

---

Firmware 3.57 installed on FL SWITCH 2116  
Order number: 2702908

---

Firmware 3.57 installed on FL SWITCH 2204-2TC-2SFX  
Order number: 2702334

---

Firmware 3.57 installed on FL SWITCH 2205  
Order number: 2702326

---

Firmware 3.57 installed on FL SWITCH 2206-2FX  
Order number: 2702330

---

Firmware 3.57 installed on FL SWITCH 2206-2FX SM  
Order number: 2702331

---

---

**Product**

---

Firmware 3.57 installed on FL SWITCH 2206-2FX SM ST  
Order number: 2702333

---

Firmware 3.57 installed on FL SWITCH 2206-2FX ST  
Order number: 2702332

---

Firmware 3.57 installed on FL SWITCH 2206-2SFX  
Order number: 2702969

---

Firmware 3.57 installed on FL SWITCH 2206-2SFX PN  
Order number: 1044028

---

Firmware 3.57 installed on FL SWITCH 2206C-2FX  
Order number: 1095628

---

Firmware 3.57 installed on FL SWITCH 2207-FX  
Order number: 2702328

---

Firmware 3.57 installed on FL SWITCH 2207-FX SM  
Order number: 2702329

---

Firmware 3.57 installed on FL SWITCH 2208  
Order number: 2702327

---

Firmware 3.57 installed on FL SWITCH 2208 PN  
Order number: 1044024

---

Firmware 3.57 installed on FL SWITCH 2208C  
Order number: 1095627

---

Firmware 3.57 installed on FL SWITCH 2212-2TC-2SFX  
Order number: 2702907

---

Firmware 3.57 installed on FL SWITCH 2214-2FX  
Order number: 2702905

---

Firmware 3.57 installed on FL SWITCH 2214-2FX SM  
Order number: 2702906

---

Firmware 3.57 installed on FL SWITCH 2214-2SFX  
Order number: 1006188

---

Firmware 3.57 installed on FL SWITCH 2214-2SFX PN  
Order number: 1044030

---

Firmware 3.57 installed on FL SWITCH 2216  
Order number: 2702904

---

Firmware 3.57 installed on FL SWITCH 2216 PN  
Order number: 1044029

---

Firmware 3.57 installed on FL SWITCH 2303-8SP1  
Order number: 1278397

---

Firmware 3.57 installed on FL SWITCH 2304-2GC-2SFP  
Order number: 2702653

---

Firmware 3.57 installed on FL SWITCH 2306-2SFP  
Order number: 2702970

---

Firmware 3.57 installed on FL SWITCH 2306-2SFP PN  
Order number: 1009222

---

Firmware 3.57 installed on FL SWITCH 2308  
Order number: 2702652

---

Firmware 3.57 installed on FL SWITCH 2308 PN  
Order number: 1009220

---

Firmware 3.57 installed on FL SWITCH 2312-2GC-2SFP  
Order number: 2702910

---

---

**Product**

---

Firmware 3.57 installed on FL SWITCH 2314-2SFP  
Order number: 1006191

---

Firmware 3.57 installed on FL SWITCH 2314-2SFP PN  
Order number: 1031683

---

Firmware 3.57 installed on FL SWITCH 2316  
Order number: 2702909

---

Firmware 3.57 installed on FL SWITCH 2316 PN  
Order number: 1031673

---

Firmware 3.57 installed on FL SWITCH 2316/K1  
Order number: 1184084

---

Firmware 3.57 installed on FL SWITCH 2404-2TC-2SFX  
Order number: 1088853

---

Firmware 3.57 installed on FL SWITCH 2406-2SFX  
Order number: 1043414

---

Firmware 3.57 installed on FL SWITCH 2406-2SFX PN  
Order number: 1089126

---

Firmware 3.57 installed on FL SWITCH 2408  
Order number: 1043412

---

Firmware 3.57 installed on FL SWITCH 2408 PN  
Order number: 1089133

---

Firmware 3.57 installed on FL SWITCH 2412-2TC-2SFX  
Order number: 1088875

---

Firmware 3.57 installed on FL SWITCH 2414-2SFX  
Order number: 1043423

---

Firmware 3.57 installed on FL SWITCH 2414-2SFX PN  
Order number: 1089139

---

Firmware 3.57 installed on FL SWITCH 2416  
Order number: 1043416

---

Firmware 3.57 installed on FL SWITCH 2416 PN  
Order number: 1089150

---

Firmware 3.57 installed on FL SWITCH 2504-2GC-2SFP  
Order number: 1088872

---

Firmware 3.57 installed on FL SWITCH 2506-2SFP  
Order number: 1043491

---

Firmware 3.57 installed on FL SWITCH 2506-2SFP PN  
Order number: 1089135

---

Firmware 3.57 installed on FL SWITCH 2506-2SFP/K1  
Order number: 1215329

---

Firmware 3.57 installed on FL SWITCH 2508  
Order number: 1043484

---

Firmware 3.57 installed on FL SWITCH 2508 PN  
Order number: 1089134

---

Firmware 3.57 installed on FL SWITCH 2508/K1  
Order number: 1215350

---

Firmware 3.57 installed on FL SWITCH 2512-2GC-2SFP  
Order number: 1088856

---

Firmware 3.57 installed on FL SWITCH 2514-2SFP  
Order number: 1043499

---

**Product**

---

Firmware 3.57 installed on FL SWITCH 2514-2SFP PN  
Order number: 1089154

---

Firmware 3.57 installed on FL SWITCH 2516  
Order number: 1043496

---

Firmware 3.57 installed on FL SWITCH 2516 PN  
Order number: 1089205

---

Firmware 3.57 installed on FL SWITCH 2608  
Order number: 1106500

---

Firmware 3.57 installed on FL SWITCH 2608 PN  
Order number: 1106616

---

Firmware 3.57 installed on FL SWITCH 2708  
Order number: 1106615

---

Firmware 3.57 installed on FL SWITCH 2708 PN  
Order number: 1106610

---

Firmware 3.57 installed on FL NAT 2008  
Order number: 2702881

---

Firmware 3.57 installed on FL NAT 2208  
Order number: 2702882

---

Firmware 3.57 installed on FL NAT 2304-2GC-2SFP  
Order number: 2702981

---

Firmware 3.57 installed on FL SWITCH TSN 2316  
Order number: 1232304

---

Firmware 3.57 installed on FL SWITCH TSN 2312-2GC-2SFP  
Order number: 1232305

---

Firmware 3.57 installed on FL SWITCH TSN 2314-2SFP  
Order number: 1232302

---

Firmware 3.57 installed on FL SWITCH 5924-4GC  
Order number: 1525945

---

Firmware 3.57 installed on FL SWITCH 5916-8GC-4SFP+  
Order number: 1525942

---

Firmware 3.57 installed on FL SWITCH 5924SFP-4GC  
Order number: 1525944

---

Firmware 3.57 installed on FL SWITCH 5924-4SFP+  
Order number: 1525939

---

Firmware 3.57 installed on FL SWITCH 5916SFP-8GC-4SFP+  
Order number: 1525943

---

Firmware 26.06.00 installed on FL WLAN 1020  
Order number: 2702992

---

Firmware 26.06.00 installed on FL WLAN 1120  
Order number: 1386091

---

Firmware 26.06.00 installed on FL WLAN 1022  
Order number: 1752493

---

Firmware 26.06.00 installed on FL WLAN 1122  
Order number: 1752496

---

Firmware 26.06.00 installed on FL WLAN 1121  
Order number: 1386092

---

Firmware 26.06.00 installed on FL WLAN 1021  
Order number: 2702993

---

**Product**

---

Firmware 26.06.00 installed on FL WLAN 2331  
Order number: 1360276

---

Firmware 26.06.00 installed on FL WLAN 2341  
Order number: 1510249

---

Firmware 26.06.00 installed on FL WLAN 2330  
Order number: 1360275

---

Firmware 26.06.00 installed on FL WLAN 2340  
Order number: 1510147

---

Firmware 5.0.72.102 installed on TC ROUTER 4002T-4G EU  
Order number: 1234352

---

Firmware 5.0.72.102 installed on TC ROUTER 4102T-4G EU WLAN  
Order number: 1234353

---

Firmware 5.0.72.102 installed on TC ROUTER 4202T-4G EU WLAN  
Order number: 1234354

---

Firmware 5.0.71.101 installed on FL TIMESERVER NTP  
Order number: 1107132

---