

UN 38.3 Test Summary Report (Lithium Cell, Battery or Product Test Summary in Accordance with Section 2.9.4 UN Model

Regulations and Sub-section 38.3 of the UN Manual of Test and Criteria) Part III, subsection 38.3.5)

NEC Energy Solutions, Inc. 155 Flanders Road Westborough, MA 01581 508-497-7319

Cell, Battery or Product Model/Part Number(s):

□Cell 図Battery □Product ⊠Model #: *PSL000005* ☑Part #: 521811-1XX

Name: NEC Energy Solutions, Inc.			
Address: 155 Flanders Road			
City: Westborough	State: MA	ZIP: 01581 Country: USA	
Telephone: 508-497-7319		Website: www.neces.com	
t Laboratory			
Name: Shanghai Research Institute	e of Chemical Industry Testing (entre	
Address: East Yunling Road No. 34	5Building A Room 717	critic	
City: Shanghai State: ZIP: Cou			
Telephone:021-52815377-0102 E-	mail: services@sricims.com, z	hangchunxiu@sricims.com Website: http://	www.sricims.com/en/contact.aspx
Cell ⊠Battery □ Product			
⊠Lithium Ion □Lithium Metal			
	Content:		
Mass: ~950			
Unique Test Report ID Number: TR	001419		
Physical Description (dimensions, a	ppearance): 151 × 64.5 × 99.7 n	nm. ABS Plastic: black bottom case, blue cove	er.
	ppearance): 151 × 64.5 × 99.7 n	nm. ABS Plastic: black bottom case, blue cove	er.
Physical Description (dimensions, a Date of test report: 1/19/2016	ppearance): 151 × 64.5 × 99.7 n	nm. ABS Plastic: black bottom case, blue cove	?r.
	ppearance): 151 × 64.5 × 99.7 п	Results (Pass/Fail/N.A.)	Additional Comments (or indicate compliance v
Date of test report: 1/19/2016	ppearance): 151 × 64.5 × 99.7 n		Additional Comments (or indicate compliance v
Date of test report: 1/19/2016 List of Tests Conducted: 8.3.4.1 Test T.1: Altitude simulation 8.3.4.2 Test T.2: Thermal test	ppearance): 151 × 64.5 × 99.7 n	Results (Pass/Fail/N.A.)	Additional Comments (or indicate compliance v
Date of test report: 1/19/2016 List of Tests Conducted: 8.3.4.1 Test T.1: Altitude simulation	ppearance): 151 × 64.5 × 99.7 n	Results (Pass/Fail/N.A.) Pass	Additional Comments (or indicate compliance v
Date of test report: 1/19/2016 List of Tests Conducted: 8.3.4.1 Test T.1: Altitude simulation 8.3.4.2 Test T.2: Thermal test	ppearance): 151 × 64.5 × 99.7 n	Results (Pass/Fail/N.A.) Pass Pass	Additional Comments (or indicate compliance v
Date of test report: 1/19/2016 List of Tests Conducted: 8.3.4.1 Test T.1: Altitude simulation 8.3.4.2 Test T.2: Thermal test 8.3.4.3 Test T.3: Vibration 8.3.4.4 Test T.4:Shock 8.3.4.5 Test T.5:External Short Circuit	ppearance): 151 × 64.5 × 99.7 n	Results (Pass/Fail/N.A.) Pass Pass Pass	Additional Comments (or indicate compliance v
Date of test report: 1/19/2016 List of Tests Conducted: 8.3.4.1 Test T.1: Altitude simulation 8.3.4.2 Test T.2: Thermal test 8.3.4.3 Test T.3: Vibration 8.3.4.4 Test T.4:Shock	ppearance): 151 × 64.5 × 99.7 n	Results (Pass/Fail/N.A.) Pass Pass Pass Pass Pass	Additional Comments (or indicate compliance v other standards, e.g. Underwriters Laboratory):
Date of test report: 1/19/2016 List of Tests Conducted: 8.3.4.1 Test T.1: Altitude simulation 8.3.4.2 Test T.2: Thermal test 8.3.4.3 Test T.3: Vibration 8.3.4.4 Test T.4:Shock 8.3.4.5 Test T.5:External Short Circuit	ppearance): 151 × 64.5 × 99.7 n	Results (Pass/Fail/N.A.) Pass Pass Pass Pass Pass Pass	Additional Comments (or indicate compliance v
Date of test report: 1/19/2016 List of Tests Conducted: 8.3.4.1 Test T.1: Altitude simulation 8.3.4.2 Test T.2: Thermal test 8.3.4.3 Test T.3: Vibration 8.3.4.4 Test T.4:Shock 8.3.4.5 Test T.5:External Short Circuit 8.3.4.6 Test T.6: Impact/Crush	ppearance): 151 × 64.5 × 99.7 n	Pass Pass Pass Pass Pass Pass Pass Pass	Additional Comments (or indicate compliance v
Date of test report: 1/19/2016 List of Tests Conducted: 8.3.4.1 Test T.1: Altitude simulation 8.3.4.2 Test T.2: Thermal test 8.3.4.3 Test T.3: Vibration 8.3.4.4 Test T.4:Shock 8.3.4.5 Test T.5:External Short Circuit 8.3.4.6 Test T.6: Impact/Crush 8.3.4.7 Test T.7: Overcharge		Pass Pass Pass Pass Pass Pass Pass Pass	Additional Comments (or indicate compliance v
Date of test report: 1/19/2016 List of Tests Conducted: 8.3.4.1 Test T.1: Altitude simulation 8.3.4.2 Test T.2: Thermal test 8.3.4.3 Test T.3: Vibration 8.3.4.4 Test T.4:Shock 8.3.4.5 Test T.5:External Short Circuit 3.3.4.6 Test T.6: Impact/Crush 3.3.4.7 Test T.7: Overcharge 8.3.4.8 Test T.8: Forced discharge	Jun38.3.3(f) □un38.3.3(g) M J	Results (Pass/Fail/N.A.) Pass Pass Pass Pass Pass Pass Pass Pa	Additional Comments (or indicate compliance v
Date of test report: 1/19/2016 List of Tests Conducted: 8.3.4.1 Test T.1: Altitude simulation 8.3.4.2 Test T.2: Thermal test 8.3.4.3 Test T.3: Vibration 8.3.4.4 Test T.4:Shock 8.3.4.5 Test T.5:External Short Circuit 8.3.4.6 Test T.6: Impact/Crush 8.3.4.7 Test T.7: Overcharge 8.3.4.8 Test T.8: Forced discharge	Jun38.3.3(f) □un38.3.3(g) M J	Results (Pass/Fail/N.A.) Pass Pass Pass Pass Pass Pass Pass Pa	Additional Comments (or indicate compliance v
Date of test report: 1/19/2016 List of Tests Conducted: 8.3.4.1 Test T.1: Altitude simulation 8.3.4.2 Test T.2: Thermal test 8.3.4.3 Test T.3: Vibration 8.3.4.4 Test T.4:Shock 8.3.4.5 Test T.5:External Short Circuit 8.3.4.6 Test T.6: Impact/Crush 8.3.4.7 Test T.7: Overcharge 8.3.4.8 Test T.8: Forced discharge attery Assembly: Not Applicable	JUN38.3.3(f) □UN38.3.3(g) Mf Criteria, Part III, subsection 38.	Results (Pass/Fail/N.A.) Pass Pass Pass Pass Pass Pass Pass Pa	Additional Comments (or indicate compliance v

Date 8/5/19

ent contains the confidential and proprietary information of NEC Energy Solutions, Inc. and may be used solely

with authorized use and for no other purpose. This document may not be reproduced, retransmitted

or redistributed, either in whole or in part, for any reason without NEC Energy Solutions, Inc. prior written consent.

Template # SD000016 Rev. 01

PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED – SEE THE NEC ENERGY SOLUTIONS, INC. PLM SYSTEM FOR LATEST REVISION.